

# 03

**Product Control Criteria  
Before Manufacturing**

## Product Control Criteria Before Manufacturing

Before manufacturing, the application firms should carefully carry out the essential quality control procedures for porcelain slabs. The surface of the slab should be thoroughly cleaned and carefully reviewed.

The points to be considered while inspecting porcelain slabs are listed below:

- Cracks and breaks,
- Stain and deformations formed on the surface of the slab,
- Possible polishing differences on the surface of polished slabs,
- Flatness of the slab,
- Appearance of different tones in the surface color of the slab.

In preventing possible defects before starting production, it is essential to examine the points above carefully.

During the manufacturing phase of our porcelain slabs, the defects noticed before or after the assembling process will not be accepted as justification for product return or replacement. Slabs can be replaced if a defect is noticed before cutting or processing

### Flatness of the Surface

To check the flatness of porcelain slabs, you should put them on level ground and examine them with the help of a gauge, which has a smoothness you can be sure of.

#### Important

The bending tolerance of the slab from one end to the other is 2mm in width and 6mm in length.

### Tonality

Due to the natural raw materials from which it is manufactured, Slabs may include tone variations.


These differences are numbered in the color tone section of the labels on the slab.

Products with the same color and thickness and the color tone number have the same tonality.


#### Note

Slabs should be examined in an environment with adequate light during purchase or before manufacturing.

Our porcelain slabs have an identification label that contains sensitive information such as product code, color tone, size, date and time of production, quality characteristics and finishing details.



Label before opening A-Frame



Single label on the porcelain slab



Montecera USA

Office Number 850-945-8220

Florida Office: 308 Williams Ave Port St Joe, FL 32456

Georgia Office & Warehouse: 1625 Bethel Rd Bainbridge GA 39819

[www.montecera.com](http://www.montecera.com)